

Lorry Engine Repaired with Belzona

ID: 7576

Industry: *Transport*
Application: *ENC-Engines and Casings*
Substrate: *Cast iron*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Transport company, Slovakia*
Application Date: *2014*

Problem

Cracked block due to freezing over winter months



Photograph Descriptions

1. Cracked engine
2. Crack detection to identify all cracks
3. Surface preparation
4. Belzona® 1111 repair incorporating Belzona® 9341 Reinforcement Tape

Application Situation

Lorry engine.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Welding of this damage would take a long time and potentially cause more damage so repairing with Belzona® 1111 was much better for customer.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve