

Belzona Protects Settlement Tank

ID: 7565

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: Belzona® 5811 (Immersion Grade)

Customer Location: Pharmaceutical company, Slovakia
Application Date: 2010

Problem

Erosion/corrosion damage was affecting the normal operation of the equipment.



Photograph Descriptions

1. Mixing Basin
2. Extent of damage to the basin
3. Blasting of the basin
4. Completed application

Application Situation

Damage to the tank and mixing equipment.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

The Customer required a fast, high-quality solution to repair the basin. Belzona provided an effective solution to not only repair the basin and mixing apparatus, but also protect it in the long term, extending the lifetime. Spraying enabled the application to be completed within the available window.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve