

Large Storage Tank Protected with Belzona

ID: 7618

Industry: *Chemical & Petrochemical*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: *Belzona® 5811 (Immersion Grade),
Belzona® 1111 (Super Metal)*

Customer Location: *Petrochemical company,
Slovakia*
Application Date: *2015*

Problem

The tank had been in service for twenty years and was suffering extensive corrosion damage



Photograph Descriptions

1. Tank after 20 years
2. Blasting of the basin
3. Visible damages after blasting
4. Belzona® 5811 coating applied in 2 layers

Application Situation

Crude oil storage tank.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Customer needed quick and quality repair. All protection was realized with Belzona® 5811. Deep corrosion was rebuilt with Belzona® 1111.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve