

# Belzona Provides Safe Welcome

ID: 1100

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Floor tiles  
Products: Belzona® 1321 (Ceramic S-Metal),  
Belzona® 9211 (Supergrip Aggregate)

Customer Location: Manufacturer, Slovakia  
Application Date: 2008

## Problem

During rain or snow people have slip problems on the ramp into the offices.



## Photograph Descriptions

1. Ramp entrance
2. Templates being placed
3. Completed application

## Application Situation

Main entrance into companies offices.

## Application Method

Application was carried out in accordance with Instructions for use. Belzona® 1321 was applied by brush in conjunction with Belzona® 9211 (Supergrip Aggregate). Templates were used to create logo.

## Belzona Facts

Customer achieved a quick, distinctive and attractive solution. The message reads "WELCOME TO OUR FIRM SLOVCEM".

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q.09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve